




APLICAÇÃO



CARACTERÍSTICAS




DIMENSÕES E EMBALAGEM




INFORMAÇÕES TÉCNICAS

DOBRADIÇA RETA




	R	17	18	19	20	21
H=0	K	3	4	5	6	7

DOBRADIÇA CURVA






	R	8	9	10	11	12
H=9	K	3	4	5	6	7




	Gf	18	19	20	21	22	23	24	25	26	27	28	29	30	31
K=3	A=	0	0	0	0	0	0	0	0	0.5	0.5	1.0	1.5	2.5	4.0
K=4	A=	0	0	0	0	0	0	0	0	0.5	1.0	1.5	2.0	3.0	4.5
K=5	A=	0	0	0	0	0	0	0	0	0.5	1.0	1.5	2.0	3.0	4.5
K=6	A=	0	0	0	0	0	0	0	0	0.5	1.0	1.5	3.0	4.5	
K=7	A=	0	0	0	0	0	0	0	0	1.0	1.5	2.0			


MONTAGEM E AJUSTES DE REGULAGEM



K=3-7mm
Gf=espessura MDF



A Dobradiça Absoluta possui um botão que permite ligar ou desligar o amortecimento de forma rápida, sem uso de ferramentas.



10	10	FECHAMENTO AMORTECIDO
10	10	FECHAMENTO AMORTECIDO RÁPIDO
10	10	FECHAMENTO SEM AMORTECIMENTO



Faça o teste abrindo e fechando a porta após o ajuste para verificar o comportamento desejado.